



A Bureau Veritas Group Company

McKenzie Group Consulting (NSW) Pty Ltd

ACN: 093 211 995

Level 6, 189 Kent Street, Sydney NSW 2000

Tel: 02 8298 6800 Fax: 02 8298 6899

sydney@mckenzie-group.com.au

Building Certification for Crown Building Work Certificate No. 20/124846-6

Pursuant to the provisions of Section 6.28 of the Environmental Planning and Assessment Act 1979 No 203, McKenzie Group Consulting hereby certify that the building has been designed in accordance with the technical provisions of the State's building laws and in particular, the Building Code of Australia. This certification is based upon our review of the documentation submitted, including plans, specifications and certification from design consultant.

Owner

Name: Health Administration Corporation
Address: Level 14, 77 Pacific Highway, North Sydney NSW 2060

Property details

Address: Part Lot 1 DP870820 (Randwick Hospital Campus), Lot 6 DP13997 (71 Botany Street, Randwick), Lot A DP167106 (73 Botany Street Randwick), Lot B DP167106 (75 Botany Street, Randwick), Lot C DP167106 (77 Botany Street, Randwick), Lot D DP167106 (79 Botany Street, Randwick), Lot A DP33161 (81 Botany Street, Randwick), Lot B DP33161 (83 Botany Street, Randwick), Lot C DP33161 (85 Botany Street, Randwick), Lot D DP33161 (87 Botany Street, Randwick), Lot E DP33161 (89 Botany Street, Randwick), Lot F DP33161 (91 Botany Street, Randwick), Lot 1 DP741639 (93 Botany Street, Randwick), Lot 2 DP1134643 (95 Botany Street, Randwick), Lot A DP439101 (97 Botany Street, Randwick), Lot B DP439101 (99 Botany Street, Randwick) Lot 3 DP302329 (101 Botany Street, Randwick), Part Lot 2 DP13995 (27 Eurimbla Avenue, Randwick), Lot 3 DP13995 (29 Eurimbla Avenue, Randwick), Lot 4 DP13995 (31 Eurimbla Avenue, Randwick), Lot 5 DP13995 (33 Eurimbla Avenue, Randwick), Lot 6 DP13995 (35 Eurimbla Avenue, Randwick), Lot 7 DP13995 (37 Eurimbla Avenue, Randwick), Lot 8 DP13995 (39 Eurimbla Avenue, Randwick), Lot 9 DP13995 (41 Eurimbla Avenue, Randwick), Lot 10 DP13995 (43 Eurimbla Avenue, Randwick), Lot 11 DP13995 (45 Eurimbla Avenue, Randwick), Lot 12 DP13995 (47 Eurimbla Avenue, Randwick), Lot 13 DP12909 (34 Eurimbla Avenue, Randwick), Lot 14 DP12909 (36 Eurimbla Avenue, Randwick), Lot B DP441943 (38 Eurimbla Avenue, Randwick), Lot A DP441943 (40 Eurimbla Avenue, Randwick), Lot 1 DP1182570 (42 Eurimbla Avenue, Randwick), Lot 2 DP1182570 (44 Eurimbla Avenue, Randwick), Lot 23A DP434935 (46 Eurimbla Avenue, Randwick), Lot 23B DP434935 (48 Eurimbla Avenue, Randwick), Lot 1 DP522596 (50 Eurimbla Avenue, Randwick), Lot 2 DP533596 (52 Eurimbla Avenue, Randwick), Lot 1 DP501682 (54 Eurimbla Avenue, Randwick), Lot 2 DP501682 (56 Eurimbla Avenue, Randwick), Lot 3 DP 513339 (58 Eurimbla Avenue, Randwick), Lot 4 DP513339 (60 Eurimbla Avenue, Randwick), Lot 19 DP7745 (62 Eurimbla Avenue, Randwick), Lot 18 DP7745 (64-64A Eurimbla Avenue, Randwick, Randwick), Lot 52 DP7745 (64R Eurimbla Avenue – Pedestrian walkway, Randwick), Lot 1 DP748060 (66 Eurimbla Avenue – also known as 6 Magill Street, Randwick), Lot 11 DP806091 (66A Eurimbla Avenue, Randwick), Lot 1 DP307266 (2 Magill Street, Randwick), Lot 12 DP806091 (4 Magill Street, Randwick), Lot Dp975640 (8-8A Magill Street, Randwick), Lot 1 DP11351 (10 Magill Street, Randwick), Lot 2 DP11351 (12 Magill Street, Randwick) Lot 3 DP11351 (14 Magill Street, Randwick)

Municipality: Randwick City Council

Description and value of development

Description: Randwick Campus Redevelopment new Acute Services Building (ASB) is the first stage of a major expansion of Prince of Wales Hospital at Randwick.

The Project scope includes a new 13 storey Acute Services Building of approximately 50,000 m² and associated Early Works Including demolition, services diversion and relocations to allow construction of the new acute services building. This new ASB will comprise of the following uses:

- Bulk earthworks
- Adults Emergency Department
- Psychiatric Emergency Care Centre
- Operating Theatres and Central Sterilising Service
- Intensive Care Unit and High Dependency Unit
- Medical Assessment Unit
- Inpatient Units
- Support Services
- Front of house areas, including retail and education/training/research (ETR) Facilities
- Overhead pedestrian links to existing hospital buildings;
- A helipad on the uppermost roof of the building;
- Magill Street road works, Botany Street signalised intersection, internal roads and drop-off/pick-up areas; and
- Utility, site infrastructure and landscaping works.

Value of work: \$75,276,544.00

Building Code of Australia building classification

Part: Works to be completed under this application are as follows:

- Complete Structure
- Services and Fit-out – B2 to Level 1 Inclusive

Use: Hospital

BCA classification: 5, 6, 7a, 9a

Determination

Approved/Refused: Approved

Date of Determination: 19 June 2020

Development Consent

Certificate no.: SSD 9113 & SSD9113-MOD1

Date of Determination: 27 February 2019

Plans and specifications approved

- MGC Approved Plans prepared by Lendlease Building numbered: RCR-BVN-ARC-50-DRW-11B-0000001[14], RCR-BVN-ARC-50-DRW-11B-0000002[14], RCR-BVN-ARC-50-DRW-11B-0100001[11], RCR-BVN-ARC-50-DRW-11B-0100002[11], RCR-BVN-ARC-50-DRW-11B-B100001[11], RCR-BVN-ARC-50-DRW-11B-B100002[11], RCR-BVN-ARC-50-DRW-11B-B200001[11], RCR-BVN-ARC-50-DRW-11B-B200002[11], RCR-BVN-ARC-50-DRW-11B-B300001[11], RCR-BVN-ARC-50-DRW-11B-B300002[11], RCR-BVN-ARC-50-DRW-12B-0010001[12], RCR-BVN-ARC-50-DRW-12B-0020001[9], RCR-BVN-ARC-50-DRW-12B-0110001[8], RCR-BVN-ARC-50-DRW-12B-0120001[7], RCR-BVN-ARC-50-DRW-12B-B120001[9], RCR-BVN-ARC-50-DRW-12B-B130001[9], RCR-BVN-ARC-50-DRW-12B-B140001[9], RCR-BVN-ARC-50-DRW-12B-B180001[7], RCR-BVN-ARC-50-DRW-12B-B190001[7], RCR-BVN-ARC-50-DRW-12B-B210001[8], RCR-BVN-ARC-50-DRW-12B-B220001[11], RCR-BVN-ARC-50-DRW-12B-B230001[8], RCR-BVN-ARC-50-DRW-12B-B240001[8], RCR-BVN-ARC-50-DRW-12B-B280001[8], RCR-BVN-ARC-50-DRW-12B-B290001[9], RCR-BVN-ARC-50-DRW-12B-B320001[7] and RCR-BVN-ARC-50-DRW-12B-NL50101[5].

Attachments

1. Fire safety schedule.
2. Application form for Crown Certificate.
3. Aboriginal Cultural Heritage Management Sub Plan prepared by Mary Dallas Consulting Archaeologist
4. Construction Traffic & Pedestrian Management Subplan Version 3 prepared by Lendlease dated July 2019

5. Management Plan Heritage and Archaeological Revision 2 prepared by Lendlease Building Pty Ltd dated 18 March 2020
6. Letter for Agreement of alternative framework prepared by Planning Industry and Environment dated 22 October 2019
7. Design Certificate for Security Works prepared by Siemens dated 5 June 2020
8. Report Development Consent B49 prepared by AviPro dated 10 March 2020
9. Structural Engineering Specifications Revision 3 prepared by Enstruct Group Pty Ltd dated February 2020
10. Statement of Compliance for End of Trip facility prepared by Team 2 Architects dated 25 September 2019
11. Randwick Hospital Redevelopment Archaeology Preliminary Finds Assessment prepared by MDCA
12. Design Certificate for Access prepared by McKenzie Group Consulting (QLD) Pty Ltd dated 18 March 2020
13. Email Correspondence regarding Green Stair Online Application Received prepared by Stantec dated 17 October 2019
14. Pile Certification prepared by Wagstaff Piling Pty Ltd dated 22 January 2020
15. Email Correspondence regarding CTPMP and CWTS Approval prepared by Transport NSW dated 19 February 2020
16. Email Correspondence regarding DPIE Approval of Alternative Strategy for ES prepared by PWC dated 16 January 2020
17. Tax invoice for GS-4699DA-A-38478 prepared by Green Building Council Australia dated 8 October 2019
18. Letter regarding Condition B40 prepared by NSW Government Planning & Environment dated 14 June 2019
19. Randwick Campus Redevelopment Management Plan Heritage and Archaeological Revision 2.5 prepared by Lendlease Building Pty Ltd dated 18 March 2020
20. Aboriginal Cultural Heritage Management Sub-Plan prepared by MDCA
21. Staging Report Version 3 NSW Government Health Infrastructure dated 24 April 2020
22. Correspondence for Survey Report to Satisfy Condition 51 dated 24 March 2020
23. Report for Development Consent B50 prepared by AviPro dated 10 March 2020
24. Flight Path 3D Survey Report prepared by AviPro dated 24 March 2020
25. Design Guideline Note for Environmentally Sustainable Development prepared by NSW Government Health Infrastructure dated 15 October 2019
26. Operational Noise Condition B61 prepared by Acoustic Logic dated 28 January 2020
27. Certificate for Traffic Management prepared by ARUP dated 4 December 2019
28. CC2 Condition B dated 29 January 2020
29. Letter regarding B62 prepared by ARUP dated 4 December 2019
30. Design Certificate for Fire Protection Services Works prepared by Innovative Fire Services dated 4 June 2020
31. Design Certificate for Pneumatic Tube Services prepared by Aircom dated 30 April 2020
32. Structural Design Statement for Crown Certification prepared by Enstruct dated 4 June 2020
33. Design Certificate for Architectural Works prepared by BVN dated 11 June 2020
34. Design Statement for Piling prepared by Wagstaff Piling dated 26 September 2019
35. CTPMP prepared by Lendlease dated July 2019
36. Long Service Levy Receipt prepared by Long Service Corporation dated 6 May 2020
37. Report for Access Design prepared by McKenzie Group Consulting (QLD) Pty Ltd dated 30 March 2020
38. Aboriginal Cultural Assessment Report prepared by MDCA dated October 2018
39. Letter regarding SSD Bicycle and End of Trip Facilities Component prepared by Team2 Architects Pty Ltd dated 25 September 2019
40. Plans for New End of Trip Facilities prepared by Team2 Architects Pty Ltd numbered: SD000[1], SD010[1], SD011[1], SD021[1], SD121[1], SD421[1] and SD521[1]
41. Section J JV3 Report Revision F prepared by LCI dated 29 May 2020
42. Hydraulic Design Statement of Compliance prepared by Central Plumbing dated 26 May 2020
43. Design Certificate for Mechanical Works prepared by Fredon Air (NSW) dated 5 June 2020
44. Design Certificate for Post Tensioning prepared by SRG dated 26 May 2020
45. Fire Engineering Report Revision C prepared by ARUP dated 4 June 2020
46. Design Certificate for Communication, Electrical and Lighting Works prepared by Fredon Industries dated 19 June 2020
47. Letter regarding Acute Services Building CC2 Condition B23 prepared by Enstruct Group Pty Ltd dated 25 September 2019
48. Independent Audit Report prepared by NGH dated 24 September 2019
49. Basement B2 Slab on Grade Structural Design Principles prepared by Enstruct Group Pty Ltd dated 23 July 2019
50. Acute Services Building CC2 Condition B22 prepared by Enstruct Group Pty Ltd dated 25 September 2019
51. Plans for Security Services prepared by Siemens Building Technologies numbered: RCR-SIE-SE-50-DRW-11B-0000001[G]
52. Plans for Wet Fire Services prepared by Intense Fire Services numbered: 0000002[C], RCR-IFS-DRW-FIR-50-ALL-00[3], RCR-IFS-DRW-FIR-50-ALL-01[3], RCR-IFS-DRW-FIR-50-ALL-02[3], RCR-IFS-DRW-FIR-50-ALL-03[3], RCR-IFS-DRW-FIR-50-ALL-04[3], RCR-IFS-DRW-FIR-50-ALL-05[3], RCR-IFS-DRW-FIR-50-ALL-06[3], RCR-IFS-DRW-FIR-50-ALL-07[3], RCR-IFS-DRW-FIR-50-ALL-08[3], RCR-IFS-DRW-FIR-50-ALL-09[3], RCR-IFS-DRW-FIR-50-ALL-10[3], RCR-IFS-DRW-FIR-50-ALL-B1[3] and RCR-IFS-DRW-FIR-50-ALL-B2[3]

53. Plans for Pnumatic Tube Services prepared by AirCom Group numbered: 4-000-00-01[1], 4-000-07-01[1], 4-000-07-02[1], 4-000-08-01[1], 4-000-08-02[1], 4-000-B1-01[1], 4-000-B1-02[1], 4-000-B2-01[1], 4-000-B2-02[1], 4-000-B2-03[1], 4-000-B2-04[1], 4-001-NL-01[1], 4-001-NL-02[1], 4-000-00-02[1], 4-000-01-01[1], 4-000-01-02[1], 4-000-02-01[1], 4-000-02-02[1], 4-000-03-01[1], 4-000-03-02[1], 4-000-04-01[1], 4-000-04-02[1], 4-000-05-01[1], 4-000-05-02[1], 4-000-06-01[1] and 4-000-06-02[1]
54. Plans for Dry Fire Services prepared by Intense Fire Services numbered: RCR-IFS-DRW-FA-50-ALL-001[1], RCR-IFS-DRW-FA-50-ALL-002[1], RCR-IFS-DRW-FA-50-ALL-00[1], RCR-IFS-DRW-FA-50-ALL-01[1], RCR-IFS-DRW-FA-50-ALL-02[1], RCR-IFS-DRW-FA-50-ALL-03[1], RCR-IFS-DRW-FA-50-ALL-04[1], RCR-IFS-DRW-FA-50-ALL-05[1], RCR-IFS-DRW-FA-50-ALL-06[1], RCR-IFS-DRW-FA-50-ALL-07[1], RCR-IFS-DRW-FA-50-ALL-08[1], RCR-IFS-DRW-FA-50-ALL-09[1], RCR-IFS-DRW-FA-50-ALL-10[1], RCR-IFS-DRW-FA-50-ALL-11[1], RCR-IFS-FA-50-ALL-B1[1] and RCR-IFS-DRW-FA-50-ALL-B2[1]
55. Historical Archaeology Excavation Report prepared by Casey & Lowe dated May 2020
56. Construction Compliance Report Revision 3 prepared by Lendlease dated 29 May 2020
57. Plans for Hydraulic Services prepared by Central Plumbing numbered: 00-0000000[3], DR-B100001[3], DR-B100002[3], DR-B100003[3], DR-B100004[3], DR-B200001[6], DR-B200002[6], DR-B200003[7], DR-B200004[4], DS-0000001[1], DS-0000002[1], DS-0000003[4], DS-0000004[1], DS-0000005[1], DS-0000007[1], DS-0000008[1], DS-0000009[2], DS-0000010[2], WG-B100001[3], WG-B100002[3], WG-B100003[3], WG-B100004[3], WG-B200001[4], WG-B200002[4], WG-B200003[5], WG-B200004[5], WG-IG00001[2], WG-IG00002[2], WG-IG00003[2], WG-IG00004[2], 00-0000001[3], DR-0000001[1], DR-0000002[1], DR-0100001[H], DR-0100002[H], DS-0000006[C], WG-0000001[1], WG-0000002[1], WG-0100001[G] and WG-0100002[G]
58. Construction Compliance Report 2 prepared by Lendlease dated 11 June 2020
59. Contractor Licence for Lendlease Building Pty Ltd
60. Design Compliance Intent Certificate Security prepared by Siemens dated 5 June 2020
61. Design Certificate for 5500AP Lift Works prepared by Schindler Lifts Australia dated 26 May 2020
62. Design Certificate for S7000 Lift Works prepared by Schindler Lifts Australia dated 26 May 2020
63. Plans for Electrical Services prepared by Fredon numbered: RCR-FRE-EL-50-SPD-0-001-NL-0[02], RCR-FRE-EL-50-SPD-0-011-NL-0[02], RCR-FRE-EL-50-SPD-0-012-NL-0[02], RCR-FRE-EL-50-SPD-0-051-NL-0[01], RCR-FRE-EL-50-SPD-0-052-NL-0[01], RCR-FRE-EL-50-SPD-0-053-NL-0[01], RCR-FRE-EL-50-SPD-0-111-NL-0[02], RCR-FRE-EL-50-SPD-0-112-NL-0[02], RCR-FRE-EL-50-SPD-0-113-NL-0[02], RCR-FRE-EL-50-SPD-0-121-NL-0[02], RCR-FRE-EL-50-SPD-0-122-NL-0[02], RCR-FRE-EL-50-SPD-0-131-NL-0[02], RCR-FRE-EL-50-SPD-0-132-NL-0[02], RCR-FRE-EL-50-SPD-0-141-NL-0[02], RCR-FRE-EL-50-SPD-0-161-NL-0[02], RCR-FRE-EL-50-SPD-0-191-NL-0[02], RCR-FRE-EL-50-SPD-0-201-NL-0[01], RCR-FRE-EL-50-SPD-0-251-NL-0[01], RCR-FRE-EL-50-SPD-0-301-NL-0[01], RCR-FRE-EL-50-SPD-0-402-NL-0[01], RCR-FRE-EL-50-SPD-0-402-NL-0[01], RCR-FRE-EL-50-SPD-1-000-00-1[01], RCR-FRE-EL-50-SPD-1-000-00-2[01], RCR-FRE-EL-50-SPD-1-000-00-5[01], RCR-FRE-EL-50-SPD-1-000-01-1[01], RCR-FRE-EL-50-SPD-1-000-01-2[01], RCR-FRE-EL-50-SPD-1-000-B1-1[01], RCR-FRE-EL-50-SPD-1-000-B1-1[02], RCR-FRE-EL-50-SPD-1-000-B1-2[02], RCR-FRE-EL-50-SPD-1-000-B1-3[02], RCR-FRE-EL-50-SPD-1-000-B1-4[02], RCR-FRE-EL-50-SPD-1-000-B2-1[03], RCR-FRE-EL-50-SPD-1-000-B2-1[03], RCR-FRE-EL-50-SPD-1-000-B2-3[03], RCR-FRE-EL-50-SPD-1-000-B2-4[03], RCR-FRE-EL-50-SPD-1-000-NL-5[01], RCR-FRE-EL-50-SPD-2-000-00-1[01], RCR-FRE-EL-50-SPD-2-000-00-2[01], RCR-FRE-EL-50-SPD-2-000-01-1[01], RCR-FRE-EL-50-SPD-2-000-01-2[01], RCR-FRE-EL-50-SPD-2-000-B1-0[01], RCR-FRE-EL-50-SPD-2-000-B1-1[02], RCR-FRE-EL-50-SPD-2-000-B1-2[02], RCR-FRE-EL-50-SPD-2-000-B1-3[02], RCR-FRE-EL-50-SPD-2-000-B1-4[02], RCR-FRE-EL-50-SPD-2-000-B2-1[03], RCR-FRE-EL-50-SPD-2-000-B2-2[03], RCR-FRE-EL-50-SPD-2-000-B2-3[03], RCR-FRE-EL-50-SPD-2-000-B2-4[03], RCR-FRE-EL-50-SPD-2-000-NL-0[01], RCR-FRE-EL-50-SPD-3-000-00-1[01], RCR-FRE-EL-50-SPD-3-000-00-2[01], RCR-FRE-EL-50-SPD-3-000-01-1[01], RCR-FRE-EL-50-SPD-3-000-01-2[01], RCR-FRE-EL-50-SPD-3-000-B1-1[02], RCR-FRE-EL-50-SPD-3-000-B1-2[02], RCR-FRE-EL-50-SPD-3-000-B1-3[02], RCR-FRE-EL-50-SPD-3-000-B1-4[02], RCR-FRE-EL-50-SPD-3-000-B2-1[02], RCR-FRE-EL-50-SPD-3-000-B2-2[02], RCR-FRE-EL-50-SPD-3-000-B2-3[02], RCR-FRE-EL-50-SPD-3-000-B2-4[02], RCR-FRE-EL-50-SPD-3-001-00-0[01], RCR-FRE-EL-50-SPD-3-001-01-0[01], RCR-FRE-EL-50-SPD-3-001-B1-0[02], RCR-FRE-EL-50-SPD-3-001-B2-0[02], RCR-FRE-EL-50-SPD-3-003-B2-0[02], RCR-FRE-EL-50-SPD-3-004-B2-0[02], RCR-FRE-EL-50-SPD-3-005-B2-0[02], RCR-FRE-EL-50-SPD-3-006-B2-0[02], RCR-FRE-EL-50-SPD-3-007-B2-0[02], RCR-FRE-EL-50-SPD-4-000-00-1[01], RCR-FRE-EL-50-SPD-4-000-00-2[01], RCR-FRE-EL-50-SPD-4-000-01-1[01], RCR-FRE-EL-50-SPD-4-000-01-2[01], RCR-FRE-EL-50-SPD-4-000-B1-1[02], RCR-FRE-EL-50-SPD-4-000-B1-2[03], RCR-FRE-EL-50-SPD-4-000-B1-3[02], RCR-FRE-EL-50-SPD-4-000-B1-4[03], RCR-FRE-EL-50-SPD-4-000-B2-1[02], RCR-FRE-EL-50-SPD-4-000-B2-2[03], RCR-FRE-EL-50-SPD-4-000-B2-3[02], RCR-FRE-EL-50-SPD-4-000-B2-4[03], RCR-FRE-EL-50-SPD-5-020-00-0[01], RCR-FRE-EL-50-SPD-5-020-01-1[01], RCR-FRE-EL-50-SPD-5-020-01-2[01], RCR-FRE-EL-50-SPD-5-020-B1-0[02], RCR-FRE-EL-50-SPD-5-020-B2-0[02], RCR-FRE-EL-50-SPD-5-023-02-0[01], RCR-FRE-EL-50-SPD-5-035-NL-0[01], RCR-FRE-EL-50-SPD-5-050-B2-0[02], RCR-FRE-EL-50-SPD-5-051-B2-0[02], RCR-FRE-EL-50-SPD-5-052-B2-0[02], RCR-FRE-EL-50-SPD-5-053-B2-0[02], RCR-FRE-EL-50-SPD-6-000-B1-1[01], RCR-FRE-EL-50-SPD-6-000-B1-3[01], RCR-FRE-EL-50-SPD-6-000-B2-1[03], RCR-FRE-EL-50-SPD-6-000-B2-2[03], RCR-FRE-EL-50-SPD-7-000-B1-4[01], RCR-FRE-EL-50-SPD-7-000-B2-1[02], RCR-FRE-EL-50-SPD-7-000-B2-2[02], RCR-FRE-EL-50-SPD-7-000-B2-3[02], RCR-FRE-EL-50-SPD-7-000-B2-4[02], RCR-FRE-EL-50-SPD-7-000-NL-5[01], RCR-FRE-EL-50-SPD-8-000-00-0[02], RCR-FRE-EL-50-SPD-8-000-00-0[01], RCR-FRE-EL-50-SPD-8-000-01-0[02], RCR-FRE-EL-50-SPD-8-000-01-0[01], RCR-FRE-EL-50-SPD-8-000-B1-0[02], RCR-FRE-EL-50-SPD-8-000-B1-0[01], RCR-FRE-EL-50-SPD-

8-000-B2-0[02], RCR-FRE-EL-50-SPD-8-000-B2-0[01], RCR-FRE-EL-50-SPD-6-000-B2-3[03], RCR-FRE-EL-50-SPD-6-000-B2-4[05], RCR-FRE-EL-50-SPD-6-001-B2-0[01], RCR-FRE-EL-50-SPD-6-002-B2-0[01], RCR-FRE-EL-50-SPD-6-003-B2-0[01], RCR-FRE-EL-50-SPD-7-000-00-1[01], RCR-FRE-EL-50-SPD-7-000-00-2[01], RCR-FRE-EL-50-SPD-7-000-00-5[01], RCR-FRE-EL-50-SPD-7-000-01-1[01], RCR-FRE-EL-50-SPD-7-000-01-2[01], RCR-FRE-EL-50-SPD-7-000-B1-1[01], RCR-FRE-EL-50-SPD-7-000-B1-2[01] and RCR-FRE-EL-50-SPD-7-000-B1-3[01].

64. Plans for Structural Design prepared by Enstruct Group numbered: RCR-ENS-STR-50-DRW-000-00[10], RCR-ENS-STR-50-DRW-000-01[10], RCR-ENS-STR-50-DRW-001-01[11], RCR-ENS-STR-50-DRW-005-01[10], RCR-ENS-STR-50-DRW-005-02[12], RCR-ENS-STR-50-DRW-005-03[14], RCR-ENS-STR-50-DRW-005-04[14], RCR-ENS-STR-50-DRW-005-05[12], RCR-ENS-STR-50-DRW-005-31[7], RCR-ENS-STR-50-DRW-005-35[4], RCR-ENS-STR-50-DRW-005-41[8], RCR-ENS-STR-50-DRW-005-42[5], RCR-ENS-STR-50-DRW-005-45[1], RCR-ENS-STR-50-DRW-005-51[5], RCR-ENS-STR-50-DRW-005-52[6], RCR-ENS-STR-50-DRW-005-53[4], RCR-ENS-STR-50-DRW-005-54[3], RCR-ENS-STR-50-DRW-005-55[3], RCR-ENS-STR-50-DRW-005-61[10], RCR-ENS-STR-50-DRW-005-62[10], RCR-ENS-STR-50-DRW-005-63[10], RCR-ENS-STR-50-DRW-005-64[10], RCR-ENS-STR-50-DRW-005-65[10], RCR-ENS-STR-50-DRW-005-66[12], RCR-ENS-STR-50-DRW-005-67[10], RCR-ENS-STR-50-DRW-005-68[10], RCR-ENS-STR-50-DRW-005-69[10], RCR-ENS-STR-50-DRW-005-70[10], RCR-ENS-STR-50-DRW-005-71[10], RCR-ENS-STR-50-DRW-005-72[10], RCR-ENS-STR-50-DRW-005-73[10], RCR-ENS-STR-50-DRW-005-74[10], RCR-ENS-STR-50-DRW-005-75[10], RCR-ENS-STR-50-DRW-005-76[10], RCR-ENS-STR-50-DRW-005-77[11], RCR-ENS-STR-50-DRW-005-78[11], RCR-ENS-STR-50-DRW-005-79[10], RCR-ENS-STR-50-DRW-005-80[11], RCR-ENS-STR-50-DRW-005-81[10], RCR-ENS-STR-50-DRW-005-82[11], RCR-ENS-STR-50-DRW-005-83[7], RCR-ENS-STR-50-DRW-005-90[1], RCR-ENS-STR-50-DRW-005-91[10], RCR-ENS-STR-50-DRW-005-92[3], RCR-ENS-STR-50-DRW-005-93[2], RCR-ENS-STR-50-DRW-005-94[C], RCR-ENS-STR-50-DRW-005-95[A], RCR-ENS-STR-50-DRW-005-96[4], RCR-ENS-STR-50-DRW-005-97[2], RCR-ENS-STR-50-DRW-005-98[3], RCR-ENS-STR-50-DRW-005-99[2], RCR-ENS-STR-50-DRW-006-11[C], RCR-ENS-STR-50-DRW-006-12[B], RCR-ENS-STR-50-DRW-006-13[B], RCR-ENS-STR-50-DRW-006-14[B], RCR-ENS-STR-50-DRW-006-15[B], RCR-ENS-STR-50-DRW-006-16[B], RCR-ENS-STR-50-DRW-006-17[B], RCR-ENS-STR-50-DRW-006-18[B], RCR-ENS-STR-50-DRW-006-19[B], RCR-ENS-STR-50-DRW-006-20[B], RCR-ENS-STR-50-DRW-006-21[H], RCR-ENS-STR-50-DRW-006-22[H], RCR-ENS-STR-50-DRW-006-23[I], RCR-ENS-STR-50-DRW-006-24[H], RCR-ENS-STR-50-DRW-006-25[H], RCR-ENS-STR-50-DRW-006-26[E], RCR-ENS-STR-50-DRW-006-27[E], RCR-ENS-STR-50-DRW-006-28[C], RCR-ENS-STR-50-DRW-006-31[D], RCR-ENS-STR-50-DRW-006-32[C], RCR-ENS-STR-50-DRW-006-35[B], RCR-ENS-STR-50-DRW-006-36[B], RCR-ENS-STR-50-DRW-006-37[B], RCR-ENS-STR-50-DRW-006-38[B], RCR-ENS-STR-50-DRW-006-39[B], RCR-ENS-STR-50-DRW-006-40[B], RCR-ENS-STR-50-DRW-006-41[5], RCR-ENS-STR-50-DRW-006-42[5], RCR-ENS-STR-50-DRW-006-60[D], RCR-ENS-STR-50-DRW-006-61[D], RCR-ENS-STR-50-DRW-007-00[8], RCR-ENS-STR-50-DRW-009-00[5], RCR-ENS-STR-50-DRW-009-01[5], RCR-ENS-STR-50-DRW-009-02[4], RCR-ENS-STR-50-DRW-009-03[4], RCR-ENS-STR-50-DRW-009-04[4], RCR-ENS-STR-50-DRW-009-05[3], RCR-ENS-STR-50-DRW-009-06[6], RCR-ENS-STR-50-DRW-009-07[5], RCR-ENS-STR-50-DRW-009-08[4], RCR-ENS-STR-50-DRW-009-09[2], RCR-ENS-STR-50-DRW-009-10[5], RCR-ENS-STR-50-DRW-009-11[A], RCR-ENS-STR-50-DRW-009-31[6], RCR-ENS-STR-50-DRW-010-31[3], RCR-ENS-STR-50-DRW-010-32[1], RCR-ENS-STR-50-DRW-010-33[1], RCR-ENS-STR-50-DRW-010-34[2], RCR-ENS-STR-50-DRW-010-35[1], RCR-ENS-STR-50-DRW-010-40[2], RCR-ENS-STR-50-DRW-010-50[I], RCR-ENS-STR-50-DRW-011-31[N], RCR-ENS-STR-50-DRW-011-32[F], RCR-ENS-STR-50-DRW-011-41[L], RCR-ENS-STR-50-DRW-011-42[K], RCR-ENS-STR-50-DRW-013-00[11], RCR-ENS-STR-50-DRW-013-01[R], RCR-ENS-STR-50-DRW-013-02[R], RCR-ENS-STR-50-DRW-013-03[M], RCR-ENS-STR-50-DRW-013-04[10], RCR-ENS-STR-50-DRW-013-10[N], RCR-ENS-STR-50-DRW-013-11[L], RCR-ENS-STR-50-DRW-013-12[L], RCR-ENS-STR-50-DRW-013-31[H], RCR-ENS-STR-50-DRW-013-32[I], RCR-ENS-STR-50-DRW-013-33[F], RCR-ENS-STR-50-DRW-013-90[F], RCR-ENS-STR-50-DRW-014-01[7], RCR-ENS-STR-50-DRW-014-02[I], RCR-ENS-STR-50-DRW-014-21[6], RCR-ENS-STR-50-DRW-014-31[6], RCR-ENS-STR-50-DRW-014-32[C], RCR-ENS-STR-50-DRW-014-90[E], RCR-ENS-STR-50-DRW-015-01[D], RCR-ENS-STR-50-DRW-015-02[D], RCR-ENS-STR-50-DRW-015-31[D], RCR-ENS-STR-50-DRW-015-32[C], RCR-ENS-STR-50-DRW-016-01[H], RCR-ENS-STR-50-DRW-016-21[H], RCR-ENS-STR-50-DRW-016-22[D], RCR-ENS-STR-50-DRW-098-00[9], RCR-ENS-STR-50-DRW-098-01[12], RCR-ENS-STR-50-DRW-098-02[15], RCR-ENS-STR-50-DRW-098-03[5], RCR-ENS-STR-50-DRW-098-04[8], RCR-ENS-STR-50-DRW-098-08[5], RCR-ENS-STR-50-DRW-098-09[7], RCR-ENS-STR-50-DRW-098-31[9], RCR-ENS-STR-50-DRW-098-32[10], RCR-ENS-STR-50-DRW-098-33[2], RCR-ENS-STR-50-DRW-098-35[13], RCR-ENS-STR-50-DRW-098-41[D], RCR-ENS-STR-50-DRW-098-51[I], RCR-ENS-STR-50-DRW-098-52[C], RCR-ENS-STR-50-DRW-098-53[C], RCR-ENS-STR-50-DRW-098-71[4], RCR-ENS-STR-50-DRW-098-72[C], RCR-ENS-STR-50-DRW-098-81[F], RCR-ENS-STR-50-DRW-098-82[C], RCR-ENS-STR-50-DRW-098-83[B], RCR-ENS-STR-50-DRW-098-91[B], RCR-ENS-STR-50-DRW-099-00[6], RCR-ENS-STR-50-DRW-099-01[10], RCR-ENS-STR-50-DRW-099-02[11], RCR-ENS-STR-50-DRW-099-03[6], RCR-ENS-STR-50-DRW-099-04[6], RCR-ENS-STR-50-DRW-099-06[E], RCR-ENS-STR-50-DRW-099-07[B], RCR-ENS-STR-50-DRW-099-08[4], RCR-ENS-STR-50-DRW-099-09[5], RCR-ENS-STR-50-DRW-099-10[7], RCR-ENS-STR-50-DRW-099-11[6], RCR-ENS-STR-50-DRW-099-20[4], RCR-ENS-STR-50-DRW-099-21[4], RCR-ENS-STR-50-DRW-099-30[1], RCR-ENS-STR-50-DRW-099-31[1], RCR-ENS-STR-50-DRW-099-32[4], RCR-ENS-STR-50-DRW-099-33[5], RCR-ENS-STR-50-DRW-099-34[4], RCR-ENS-STR-50-DRW-099-35[3], RCR-ENS-STR-50-DRW-099-36[5], RCR-ENS-STR-50-DRW-099-40[5], RCR-ENS-STR-50-DRW-099-45[3], RCR-ENS-STR-50-DRW-099-46[4], RCR-ENS-STR-50-DRW-099-51[H], RCR-ENS-STR-50-DRW-099-71[I], RCR-ENS-STR-50-DRW-099-72[I], RCR-ENS-STR-50-DRW-099-81[F], RCR-ENS-STR-50-DRW-100-00[2], RCR-ENS-STR-50-DRW-100-01[6], RCR-ENS-STR-50-DRW-

100-02[7], RCR-ENS-STR-50-DRW-100-06[D], RCR-ENS-STR-50-DRW-100-07[B], RCR-ENS-STR-50-DRW-100-31[3], RCR-ENS-STR-50-DRW-100-32[2], RCR-ENS-STR-50-DRW-100-35[A], RCR-ENS-STR-50-DRW-100-36[B], RCR-ENS-STR-50-DRW-100-51[F], RCR-ENS-STR-50-DRW-100-52[F], RCR-ENS-STR-50-DRW-101-00[P], RCR-ENS-STR-50-DRW-101-01[5], RCR-ENS-STR-50-DRW-101-02[5], RCR-ENS-STR-50-DRW-101-06[A], RCR-ENS-STR-50-DRW-101-31[1], RCR-ENS-STR-50-DRW-101-41[A], RCR-ENS-STR-50-DRW-102-00[2], RCR-ENS-STR-50-DRW-102-01[5], RCR-ENS-STR-50-DRW-102-02[4], RCR-ENS-STR-50-DRW-102-06[A], RCR-ENS-STR-50-DRW-102-31[2], RCR-ENS-STR-50-DRW-102-35[A], RCR-ENS-STR-50-DRW-103-00[2], RCR-ENS-STR-50-DRW-103-01[4], RCR-ENS-STR-50-DRW-103-02[4], RCR-ENS-STR-50-DRW-103-06[A], RCR-ENS-STR-50-DRW-103-10[B], RCR-ENS-STR-50-DRW-103-31[2], RCR-ENS-STR-50-DRW-104-00[2], RCR-ENS-STR-50-DRW-104-01[4].

Certificate / Certifying Authority



Signature

Signed by: Paul Curjak

Date of Endorsement: 19 June 2020
Certificate Number: 20/124846-6